

# Work Order ID 88030

\*88030\*

Page 1

Wednesday, July 25, 2012 1:30:30 PM

Item ID: D2938-2 Accept \*N900040100\* Setup Start \*NS1\*  
Revision ID: Stop \*NS2\*  
Item Name: Saddle RH Out, 206  
Start Date: 7/24/2012 Start Qty: 1.00 \*1\* Cust Item ID:  
Required Date: 7/25/2012 Req'd Qty: 1.00 \*1\* Customer: CU-DAR001  
Reference: RMA RA111382 - RETURN

Approvals: Process Plan: UMF Date: 7-25-12 Tooling: \_\_\_\_\_ Date: \_\_\_\_\_ Run Start \*NR1\*  
QC: \_\_\_\_\_ Date: \_\_\_\_\_ SPC (Y/N): \_\_\_\_\_ Date: \_\_\_\_\_ Stop \*NR2\*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D2938	Rev C								

100 0.00  
\*100\*  
QC  
Quality Control  
Memo  
INSPECT RA 111382 D2938-2 B 75102  
X 1  
SADDLE IS GOOD TO PUT BACK IN STOCK  
ID UNDER NEW BATCH NUMBER

110 0.00  
\*110\*  
Packaging  
Packaging  
Identify as per dwg & Stock Location: 428  
Memo

DAS  
16  
9-89  
7/24/12

(SC)

6/7/305

**Work Order ID 88030****\*88030\***

Page 2

Wednesday, July 25, 2012 1:30:30 PM

Item ID: D2938-2

Accept

**\*N900040100\***Setup Start **\*NS1\***

Revision ID:

Item Name: Saddle RH Out, 206

Stop **\*NS2\***

Start Date: 7/24/2012 Start Qty: 1.00

**\*1\***

Cust Item ID:

Required Date: 7/25/2012 Req'd Qty: 1.00

**\*1\***

Customer: CU-DAR001

Reference: RMA RA111382

Approvals:

Process Plan: \_\_\_\_\_

Date: \_\_\_\_\_

Tooling: \_\_\_\_\_

Date: \_\_\_\_\_

Run Start **\*NR1\***

QC: \_\_\_\_\_

Date: \_\_\_\_\_

SPC (Y/N): \_\_\_\_\_

Date: \_\_\_\_\_

Stop **\*NR2\***Sequence ID/  
Work Center IDOperation  
DescriptionSet Up/  
Run Hours

Tool ID

Tool #

Plan  
CodeAccept  
QtyReject  
QtyReject  
NumberInsp.  
Stamp

120

QC21- Final Inspection - Work Order Release

0.00


**\*120\***

QC

Memo

0.00

Quality Control

12/1/31 

u 1207.30

# Picklist Print

Wednesday, July 25, 2012 1:30:33 PM

Page 1

Work Order ID: 88030

Parent Item: D2938-2

Parent Item Name: Saddle RH Out, 206

Start Date: 7/24/2012

Required Date: 7/25/2012

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP: B 00.06.26 New DWG rev (mpp 2069)EC  
IPP Rev:C As per Rev C 07-03-19 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2938-2 Saddle RH Out, 206		Manufactured	No				Each	17.0000		1			

Location

Loc Qty

Loc Code

ST421

7

81806

7

ST428

9

86424

9

ST428A

1

75102

1

1 x 75102 mlf

12-07-25

# **RA111382 D2938-2 B75102**

Received @ Dart June 27<sup>th</sup>, 2012  
Inspected @ Dart July 6<sup>th</sup>, 2012

Customer: ROTORCRAFT LEASING LLC  
Customer Contact: MARIE BREAU  
Shipped from: BROUSSARD LA USA

## **Instructions for RA 111382 D2938-2 B75102**

- Needs NO touch ups
- Needs new work order to return back to Stock
- Needs new BATCH #

**Time Estimate** = 1 HOUR ONLY (stores)

**Departments Required:** Stores (restocking)

**Pictures Attached** = NO

**THIS INSTRUCTION SHEET MUST  
BE ATTACHED TO THE  
RESTOCKING WORK ORDER AT  
ALL TIMES!!!!**